

APPENDIX D
SITE PHOTOGRAPHS



Photograph 1 - Drainage ditch located adjacent to the north boundary of the property.



Photograph 2 – View of the property along the north property boundary, looking south.



Photograph 3 - View of north boundary of the property from northeast corner, looking west toward cemetery.



Photograph 4 - View of central portion of property in dirt trail area.



Photograph 5 – View of shingle debris pile observed in central portion of property.