

APPENDIX C
Photograph Logs



Photo #1:	Looking north across the northern portion of the site
-----------	---



Photo #2:	Looking east along the northern boundary of the site
-----------	--



Photo #3:	Looking south along the western boundary of the northern portion of the site
-----------	--



Photo #4:	Looking southeast across the northern portion of the site
-----------	---



Photo #5:	Looking southwest across the northern portion of the site
-----------	---



Photo #6:	Looking southwest at the former residential structure in the northern portion of the site
-----------	---



Photo #7: Looking southeast at the former shed in the northern portion of the site



Photo #8: Looking south at the former garage in the northern portion of the site



Photo #9: Looking west at the former barn in the northern portion of the site



Photo #10: Looking north at the former silo in the northern portion of the site



Photo #11: Looking southwest across the central and southern portions of the site



Photo #12: Looking southwest across the southern portion of the site



Photo #13:	Looking south along the eastern boundary in the southern portion of the site
------------	--



Photo #14:	Looking north along the western boundary of the southern portion of the site
------------	--



Photo #15:	Looking south along the western boundary of the southern portion of the site
------------	--



Photo #16:	Looking east along the southern boundary of the site
------------	--



Photo #17:	Looking south through the wooded area in the southwestern portion of the site
------------	---



Photo #18:	Looking west through the wooded area in the southwestern portion of the site
------------	--



Photo #19: Looking north at a billboard in the southern portion of the site



Photo #20: Looking north at a billboard in the southern portion of the site



Photo #21: Looking south along the western boundary of the site



Photo #22: Looking west along the creek bed in the southern portion of the site



Photo #23: Looking north at the north adjoining farmland and associated residence



Photo #24: Looking east at the east adjoining unimproved land



Photo #25:	Looking east at the south adjoining Interstate 90
------------	---



Photo #26:	Looking southwest at the south adjoining Interstate 90 and Travel Centers of America further to the south
------------	---



Photo #27:	Looking southeast at the west adjoining residence
------------	---



Photo #28:	Looking northeast at the west adjoining residence
------------	---



Photo #29:	Looking southwest at the west adjoining farmland
------------	--



Photo #30:	Looking southwest at the west adjoining farmland and associated residence
------------	---



Photo #1:	Looking east along the northern boundary of the site
-----------	--



Photo #2:	Looking west along the northern boundary of the site
-----------	--



Photo #3:	Looking south along the western boundary of the northern portion of the site
-----------	--



Photo #4:	Looking south across the northern portion of the site
-----------	---



Photo #5:	Looking north across the northern portion of the site
-----------	---



Photo #6:	Looking southeast across the central portion of the site
-----------	--



Photo #7:	Looking southeast across the central portion of the site
-----------	--



Photo #8:	Looking east across the central portion of the site
-----------	---



Photo #9:	Looking north across the central portion of the site
-----------	--



Photo #10:	Looking southeast across the east-central portion of the site
------------	---



Photo #11:	Looking southwest across the southern portion of the site
------------	---



Photo #12:	Looking north across the eastern portion of the site
------------	--



Photo #13: Looking southwest across the wooded area in the southwestern portion of the site



Photo #14: Looking south across the wooded area in the southeastern portion of the site



Photo #15: Looking southeast at the low-lying area in the northeastern portion of the site



Photo #16: Looking southwest across the north-central portion of the site



Photo #17: A view of the pole-mounted transformer along the northern boundary of the site



Photo #18: Looking east along the electrical easement at the site



Photo #19:	Looking northwest at the north adjoining residence
------------	--



Photo #20:	Looking northeast at the north adjoining farmland
------------	---



Photo #21:	Looking northeast at the north adjoining wetland
------------	--



Photo #22:	Looking east at the east adjoining properties
------------	---



Photo #23:	Looking west across the east adjoining properties
------------	---



Photo #24:	Looking west at the west adjoining residence
------------	--



Photo #1:	Looking east across the central portion of the site
-----------	---



Photo #2:	Looking north across the northern portion of the site
-----------	---



Photo #3:	Looking northwest across the northwestern portion of the site
-----------	---



Photo #4:	Looking northeast across the northeastern portion of the site
-----------	---



Photo #5:	Looking southwest across the southwestern portion of the site
-----------	---



Photo #6:	Looking south across the southwestern portion of the site
-----------	---



Photo #7:	Looking north along the western boundary of the site and western retention pond
-----------	---



Photo #8:	Looking east along the southern boundary of the site
-----------	--



Photo #9:	Looking southeast across the southeastern portion of the site
-----------	---



Photo #10:	Looking west across the southeastern portion of the site
------------	--



Photo #11:	Looking north along the eastern boundary of the site
------------	--



Photo #12:	Looking west along the southern boundary of the site
------------	--



Photo #13:	Looking southwest across the northwestern portion of the site
------------	---



Photo #14:	Looking south across the northern portion of the site
------------	---



Photo #15:	Looking east across the northern portion of the site
------------	--



Photo #16:	Looking southeast across the northern portion of the site
------------	---



Photo #17:	Looking east at the wooded area in the east-central portion of the site
------------	---



Photo #18:	Looking southeast at the soil mound in the southwestern portion of the site
------------	---



Photo #19:	Looking northwest at the top soil removal operations in the northeast portion of the site
------------	---



Photo #20:	Looking northwest across the potential wetland in the northwestern portion of the site
------------	--



Photo #21:	Looking northwest at the retention pond in the western portion of the site
------------	--



Photo #22:	Looking southeast at the retention pond in the southeastern portion of the site
------------	---



Photo #23:	Looking southwest at the creek segment in the southeastern portion of the site
------------	--



Photo #24:	Looking southwest at the north adjoining residential property
------------	---



Photo #25:	Looking north at the north adjoining vacant land
------------	--



Photo #26:	Looking northeast at the adjoining City of Lancaster operations
------------	---



Photo #27:	Looking east at the east adjoining residence
------------	--



Photo #28:	Looking northeast at the east adjoining Leisure Craft Pools
------------	---



Photo #29:	Looking southeast at 1 Lancaster Parkway
------------	--



Photo #30:	Looking east at Ripa's restaurant
------------	-----------------------------------



Photo #31: Looking southwest at Ahold American Sales



Photo #32: Looking southeast at Try-It Distribution



Photo #33: Looking southwest at Hurtubise Tire Sales



Photo #34: Looking southwest at the southwest adjoining Parker-Hannifin Corporation



Photo #35: Looking west at the west adjoining vacant land



Photo #36: Looking northwest at the west adjoining vacant land