APPENDIX C

Photograph Log

SITE PHOTOGRAPHS

Photo #1:	Looking north across the site

Photo #2:	Looking north along the western boundary of the site

Photo #3:	Looking east across the southern portion of the site

Photo #4:	Looking north along the eastern boundary of the site

Photo #5:	Looking southwest across the central portion of the site

Photo #6:	Looking south across the central portion of the site

SITE PHOTOGRAPHS

Photo #7:	Looking west across the northern portion of the site

Photo #8:	Looking north across the site

Photo #9:	Looking east across the central portion of the site

Photo #10:	Looking north across the eastern portion of the site

Photo #11:	Looking north across the site

Photo #12:	Looking northeast across the central portion of the site

SITE PHOTOGRAPHS

Photo #13:	Looking south across the northwestern portion of the site

Photo #14:	Looking southeast across the northwestern portion of the site

Photo #15:	Looking southeast at the golf cart storage area

Photo #16:	Looking north at the restrooms in the central portion of the site

Photo #17:	Looking west at the intermittent stream in the northern portion of the site

Photo #18:	View of the empty AST in the northwestern portion of the site

SITE PHOTOGRAPHS

Photo #19:	Water storage pond with sediment tank in the northwestern portion of the site

Photo #20:	Water storage pond in the northwestern portion of the site

Photo #21:	Soil cuttings drums adjacent to the water storage pond in the northwestern portion of the site

Photo #22:	Looking south at the maintenance area

Photo #23:	Looking northeast across the maintenance area

Photo #24:	Propane AST by the maintenance area

SITE PHOTOGRAPHS

Photo #25:	New oil drum in the north-central maintenance structure

Photo #26:	Interior of north-central maintenance structure

Photo #27:	Parts washer in the maintenance area

Photo #28:	Gasoline storage shed in the maintenance area

Photo #29:	1,000-gallon gasoline/diesel AST in the maintenance area

Photo #30:	Pesticide and herbicide storage shed in the maintenance area

SITE PHOTOGRAPHS

Photo #31:	Likely former AST location in the maintenance area

Photo #32:	Empty drums in the northwestern maintenance structure

Photo #33:	Used parts storage in the maintenance area

Photo #34:	North adjoining Riverside National Cemetery

Photo #35:	North adjoining Riverside National Cemetery maintenance area

Photo #36:	East adjoining unimproved land

SITE PHOTOGRAPHS

Photo #37:	Southeast adjoining unimproved land

Photo #38:	South adjoining small arms firing range

Photo #39:	Northwest adjoining landfill area (Landfill 4)

Photo #40:	West adjoining landfill area (Landfill 4)

Photo #41:	West adjoining residential neighborhood

Photo #42:	West adjoining water AST.